

## BUILDING SAFETY CERTIFICATE

No. 226 / T/S / 2025

Dated: 15-4-2025

It is certified that the existing building **Shanti Nilaya High School, Dhamnod** (name of the building or premises) at **Rampura, Maheshwar Road, Dhamnod** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	2	-	-	-	-	-

The building is owned/occupied by **Shanti Nilaya High School, Dhamnod C/o Katherina Kasper Social**

**Service Society, Dhar** (name of the Institution) have complied with the Building safety requirements in

accordance with National Building code Rules, and verified by the officers concerned. **P.W.D. Manawar**

(Name of Department/ Govt.) on **15-4-2025** (date of inspection) in the presence of **Sr. Mychelin**

**PHJC (Principal), Sr. Suma (Manager)** (name and addresses of the Manager/Secretary or his

representative) and that the building/premises is fit for occupancy for running school with effect

from **15-4-2025** for a period of **2 yr** years in accordance

with rule and subject to compliance of the specific conditions as appended.

1. Building is R.C.C. based structural frame strong & spacious
2. enough for members to occupy.
3. Building has enough windows & ventilation and free spaces for sufficient air and light
3. All required facilities according to the national building code rules are available. (4) exit facilities is poor

Issued on **15-4-2025** at **P.W.D. Manawar**

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal :

Name : **PWD(B/R) Sub-Division Manawar**

Designation : **Dist.Dhar (M.P.)**

Name & Address of Department/ Office: \_\_\_\_\_